## **XPRESS ULTRA<sup>™</sup> INSTALLATION KIT**



## EASY INSTALLATION IN UNDER 2 MINUTES

The Xpress Ultra<sup>™</sup> Installation Kit contains everything needed for installation of SC and LC Xpress Ultra<sup>™</sup> PLUS connectors. No epoxy, polishing film, or other consumables are required, and there is no need for electrical power, allowing installers to get in and out of installation sites quickly.

## **FEATURES**

- Fast installation to minimize on-site labor costs
- Compatible with conventional LC & SC connectors and adaptors
- Easy operation
- Quick assembly in under 2 minutes
- No adhesive or polishing required
- Compact tool without electric power

ORDER CODE	DESCRIPTION
RFCTK	Xpress Ultra™ Field Installation Kit with Flat Cleaver - Standard

DESCRIPTION	OCC PN
Xpress Ultra™ Field Installation Kit with Flat Cleaver - PREMIUM	RFCTK
Jacket and 250µm Fiber Stripper + 125µm Buffer Remover	RFCFS
Thermal Buffer Removal Tool	RFCTBRT
Replacement Blade Set	RFCTBRB
Lint Free Dry Wipes	RFCLFDW
Fiber Optic Cleaning Pen	RFCCP
Kevlar Scissors	RFCKS
Fiber Disposal Unit	RFCFD
Fine Permanent Marker Pen	RFCPMP
Fiber Checker	RFCSCSM
2.5mm to 1.25mm Adapter	RFCSCADAPT
Launch Cables	RFCLCB
OCC Soft Case & Termination Pad	RFCCASE
Precision Cleave Tool (Flat) - Standard	FOCT